

Manual Grease Bank Parts

Biggest problem with grease zerks is that they:
 Don't get greased
 Because they are hard to find
 People don't want to take the time and
 Machinery breaks down before it is time

- | | | | |
|---|--|---|--|
|  | 1. Grease Tubing
PN: 100R7 |  | 11. Adaptor, #4 JIC to 1/4-28, Male
PN: 21999-0682 |
|  | 2. #4 JIC Female Swivel
PN: 106CY-4-2 |  | 12. 90° Adaptor, #4 JIC to 1/4-28, Male
PN: 21999-0683 |
|  | 3. 1/8 NPT Male Swivel
PN: 113CY-2-2 |  | 13. 45° Adaptor, #4 JIC to 1/4-28, Male
PN: 21999-0684 |
|  | 4. 1/4" Tube Union Straight
PN: 2U07003 |  | 14. 100R7 Tubing - Grease Filled
PN: 21999-0686 |
|  | 5. 1/4" Tube Union 90°
PN: 2U04003 |  | 15. Adaptor, #4 JIC to 1/8 NPT Male
PN: 2404-4-2 |
|  | 6. 90°, 1/8" NPT Taper x 1/4 Tube
PN: 20-068N |  | 16. 90° Fitting, 1/4-28 Taper x 1/4 Tube
PN: 244054 |
|  | 7. 1/4-28 Taper x 1/4 Tube Straight
PN: 21999-0413 |  | 17. 90° Adaptor, #4 JIC x 1/8 NPT
PN: 2501-4-2 |
|  | 8. 13 Port Standard Grease Bank
PN: 21999-0419 |  | 18. 45° Adaptor, #4 JIC x 1/8 NPT
PN: 2503-4-2 |
|  | 9. Tubing—Grease filled
1/4 OD x 0.0625 Wall
PN: 21999-0433-GF |  | 19. Grease Zerk 1/8 NPT |
|  | 10. Tubing
1/4 OD x 0.0625 Wall
PN: 21999-0433 |  | 20. Running Tee, 1/8 NPT, Male, Female (2) |
| | |  | 21. Straight Fitting, 1/8 NPT x 1/4 Tube
PN: 68PL-4-2 |
| | |  | 22. Straight Fitting, 1/8" NPT Taper x 1/4 Tube
PN: 68PL-4-2-TP |

Manual Grease Bank System


Grease Bank Systems
 & Parts Available

Call Today!



Item	PN	Description
8	21999-0413	Manifold
19	36-110	Grease Fitting
21	68PL-4-2	Push-to-Connect, back of manifold
1	100R7	Crimp Style Tubing
3	113CY-2-2	Male Crimp Fitting

	Part Numbers	Description
1	100R7	Grease Tubing
2	106CY-4-2	#4 JIC Female Swivel, 1/8" Hose Ends (Crimp)
3	113CY-2-2	1/8 NPT Male Swivel, 1/8" Hose Ends (Crimp)
4	2U07003	1/4" Tube, Push to Connect
5	2U04003	90 Degree Tube Union, Push to Connect, 1/4" Tube
6	20-068N	90 Degree Fitting, Push to Connect, 1/4 Tube x 1/8 Male Taper Pipe
7	21999-0413	Straight Fitting, Push to Connect, 1/4-28 Taper Male to 1/4 Tube
8	21999-0419	Manifold - Grease Bank Manifold - 13 Ports
9	21999-0433-GF	Tubing Nylon 1/4" OD x 0.0625 (Grease Filled)
10	21999-0433	Tubing Nylon 1/4" OD x 0.0625 (Grease Line)
11	21999-0682	Adaptor, #4 JIC to 1/4-28 Taper Male
12	21999-0683	90° Adaptor, #4 JIC to 1/4-28 Taper Male
13	21999-0684	45° Adapter, #4 JIC to 1/4-28 Taper
14	21999-0686	100R7 Grease Filled Tubing
15	2404-4-2	Adaptor, #4 Male JIC X 1/8" Male NPT (Straight)
16	244054	90° Fitting, Push to Connect, 1/4-28 Taper Male to 1/4 Tube
17	2501-4-2	90° Adaptor, #4 JIC X 1/8 MP
18	2503-4-2	45° Adapter, #4 JIC to 1/8 NPT
19	36-110	Grease Fitting - 1/8-27 NPT (for Front of Manifold)
20	5602-2-2-2	Run Tee, 1/8" Male, Female, Female
21	68PL-4-2	Straight Fitting, Push to Connect, 1/4 Tube X 1/8 NPT - has O-ring
22	68PL-4-2-TP	Straight Fitting, Push to Connect, 1/4 Tube X 1/8 Male Taper Pipe



- 10. Tubing
1/4 OD x 0.0625 Wall
PN: 21999-0433
- 7. 1/4-28 Taper x 1/4 Tube Straight
PN: 21999-0413